




FIRST FLOOR PLAN 4-1 "C"




FIRST FLOOR PLAN 4-1 "G"





FIRST FLOOR PLAN 4-1 "A"



SECOND FLOOR PLAN 4-2 "G"





FIRST FLOOR PLAN 4-2 "E"





MT004001 S.01

Quadrant A


Site Plan 4-1 and 4-2 Projects






FIRST FLOOR PLAN 4-1 "A"


FIRST FLOOR PLAN 4-1 "C"




FIRST FLOOR PLAN 4-1 "B"





FIRST FLOOR PLAN 4-1 "A"



FIRST FLOOR PLAN 4-1 "D"




SECOND FLOOR PLAN 4-1 "D"




MT004001 S 01

Quadrant B



SEE PLAN 4-1 AND 4-2 PROJECTS



FIRST FLOOR PLAN 4-1 "A"






MAIN FLOOR PLAN



MT004001 S.01 Quadrant D


SITE PLAN 4-1 AND 4-2 PROJECTS






FIRST FLOOR PLAN 4-1 "A"


122




FIRST FLOOR PLAN 4-1 "C"




FIRST FLOOR PLAN 4-1 "B"





FIRST FLOOR PLAN 4-1 "A"



FIRST FLOOR PLAN 4-1 "D"







SECOND FLOOR PLAN 4-1 "D"




MT004001 S.01 Quadrant B

SITE PLAN 4-1 AND 4-2 PROJECTS





SECOND FLOOR PLAN 4-1 "D"




FIRST FLOOR PLAN 4-1 "D"


123, 124

Floorplan 4-1 "D" * Exposed wood components on exterior steps attached storage closets ~~are~~ have paint in poor and deteriorated condition - should be tested for lead-based paint - Per Matt LBP has been addressed



FIRST FLOOR PLAN 4-1 "B"



FIRST FLOOR PLAN 4-1 "C"





FIRST FLOOR PLAN 4-1 "A"



MT004001 S 01 Quadrant C

SITE PLAN 4-1 AND 4-2 PROJECTIONS







FIRST FLOOR PLAN 4-1 "C"

223


FIRST FLOOR PLAN 4-1 "C"




FIRST FLOOR PLAN 4-1 "G"





FIRST FLOOR PLAN 4-1 "A"



SECOND FLOOR PLAN 4-2 "G"



FIRST FLOOR PLAN 4-2 "E"




MT004002 S 01 Quadrant A

SITE PLAN 4-1 AND 4-2 PROJECTS




306


FIRST FLOOR PLAN 4-2 "E"




FIRST FLOOR PLAN 4-2 "F"




SECOND FLOOR PLAN 4-2 "F"




FIRST FLOOR PLAN 4-1 "G"





SECOND FLOOR PLAN 4-2 "G"



FIRST FLOOR PLAN 4-1 "H"






SECOND FLOOR PLAN 4-2 "H"




MT004002 S.01 Quadrant D

SITE PLAN 4-1 AND 4-2 PROJECTS






2 "G"




N 4-1 "G"


402




SECOND FLOOR PLAN 4-2 "F"



FIRST FLOOR PLAN 4-2 "F"




2 "G"




N 4-1 "G"

418



SECOND FLOOR PLAN 4-2 "F"

M1.2H



FIRST FLOOR PLAN 4-2 "F"

M1.2F

418

M1.2G